



Operating manual

Calib-Box and software PQ-Calib
for Power Quality Analyser
PQ-Box 50; PQ-Box 100; PQ-Box 150;
PQ-Box 200 and PQ-Box 300



Ver. 06-2020



Note:

Please note that this operating manual cannot describe the latest version of the device in all cases. For example, if you download a more recent firmware version from the internet, the following description may no longer be accurate in every point.

In this case, either contact us directly or refer to the most recent version of the operating manual, available on our website (www.a-eberle.de).

A. Eberle GmbH & Co. KG

Frankenstraße 160

D-90461 Nuernberg

Tel.: 0911 / 62 81 08 0

Fax: 0911 / 62 81 08 96

E-Mail: info@a-eberle.de

Internet: www.a-eberle.de

A.-Eberle GmbH & Co. KG cannot be held liable for any damage or losses, resulting from printing errors or changes to this operating manual.

Furthermore, **A. Eberle GmbH & Co. KG** does not assume responsibility for any damage or losses resulting from defective devices or from devices altered by the user.

Copyright 2020 by A. Eberle GmbH & Co. KG

All rights reserved.

Content

1.	User prompt	4
1.1	Target group.....	4
1.2	Warnings	4
1.3	Tips	4
1.4	Other symbols	5
1.5	Applicable documentation.....	5
1.6	Keeping	5
2.	Safety information	6
2.1	Meaning of the symbols used on the device	6
3.	Warranty conditions	7
3.1	Cleaning / Maintenance	7
4.	Intended use	7
5.	PQCalib-SW.....	8
5.1	Installation of the PQCalib-SW.....	8
5.2	Open PQCalib-SW	8
5.3	WinPQ mobil	8
6.	Hardware Calib-Box	9
6.1	Operating conditions	9
6.2	Requirements for calibration equipment	10
6.3	Calibration conditions	10
6.4	Overview of the Calib-Box.....	11
6.5	PQ-Box connection to Calib-Box	12
7.	Software PQCalib	14
7.1	Calibration of PQ-Box.....	16
7.2	Start of PQ Box adjustment	17

1. User prompt



The user manual contains all important information for installation, commissioning and operation. Read the user manual completely and do not use the product until you have understood it.

1.1 Target group

These operating instructions are intended for trained and qualified staff as well as trained and tested operators. The contents of these operating instructions must be made accessible to the persons responsible for installing and operating the system.


1.2 Warnings

▶ Structure of the warnings


 SIGNAL WORD	Type and source of danger! Consequences of non-observance  Action to avoid the danger.
---	---

▶ Types of warnings


Warnings differ according to the type of danger as follows:

 DANGER!	Warns of an imminent danger which, if not avoided, will result in death or serious injury.
---	--



 WARNING!	Warns of a potentially dangerous situation that can result in death or serious injuries when not avoided.
--	---



 CAUTION!	Warns of a potentially dangerous situation that can result in fairly serious or minor injuries when not avoided.
--	--



NOTICE!	Warns of a potentially dangerous situation that if not avoided could result in material or environmental damage.
----------------	--

1.3 Tips



Notes on appropriate use of the device.

1.4 Other symbols

Instructions

Structure of the instructions:

- ➔ Guidance for an action.
- 👉 Indication of an outcome, if necessary.

Lists

Structure of unnumbered lists:

- List level 1
- List level 2

Structure of numbered lists:

- 1) List level 1
- 2) List level 1
 - 1. List level 2
 - 2. List level 2

1.5 Applicable documentation

For the safe and correct use of the product, observe the additional documentation that is delivered with the system as well as the relevant standards and laws.

1.6 Keeping

Keep the user manual, including the supplied documentation, readily accessible near the system.

2. Safety information

Please read this section carefully for important safety information.

Do not use the device for any other purpose than for measuring voltage and currents within the specified ranges and categories including the voltage to ground.



Danger to life due to electric shock!

If the analyser and calibration equipment is not used according the manual and safety instructions, the protection provided may be impaired.

- Follow the user manuals.
- Keep the user manual with the device.
- Ensure that the device is operated only in a perfect condition.
- Never open the device.
- Ensure that only qualified personnel operate the device.
- Connect the device only as specified.
- Ensure that the device is operated only in the original condition.
- Connect the device only with recommended accessories.
- Ensure that the device is not operated outside the design limits.
(see chapter **Fehler! Verweisquelle konnte nicht gefunden werden.**)
- Ensure that the original accessories are not operated outside the design limits.
- Do not use the device in environments where explosive gases, dust or fumes occur.
- Check the power supply, measuring voltage and current leads for damage before use.

2.1 Meaning of the symbols used on the device



Nature and source of the danger! Read the safety instructions inside the manual!

3. Warranty conditions

The warranty for the Calib-Box and accessories is three years in use, under normal operating conditions.

3.1 Cleaning / Maintenance

Cleaning:

The Calib-Box should not be opened for cleaning purposes. Do not use solvents for cleaning nor immerse the device in liquid.

Caution:

Don't open the Calib-Box under any circumstances! The opening can result in electric shock.

The Calib-Box contains no user-serviceable parts.

Service Address:

A. Eberle GmbH
Frankenstraße 160
D-90461 Nuernberg

4. Intended use



Danger to life due to electric shock!

Do not connect the voltage input of the device to the supply network.
Only suitable for connection to a calibrator.





There is a risk if the device is used in a manner not specified by the manufacturer

- ➞ Before making any connections, please read this manual thoroughly and follow the safety measures described here.

5. PQCalib-SW


5.1 Installation of the PQCalib-SW

Extract the file “installPQ-Calib.exe” to one folder of your choice.

 installPQCalib_V1_100	27.04.2020 15:50	Dateiordner
 installPQCalib_V1_100	13.03.2019 13:29	Anwendung

5.2 Open PQCalib-SW

To open the Calib-software please activate the PQCalib.exe file.



5.3 WinPQ mobil

It is necessary to install the the WinPQ mobil analysis software on the same PC.

You have to connect one PQ-Box with USB connection to install the hardware driver of the device.

The device driver is only included in the WinPQ mobil for communication with PQ-Box 50, PQ-Box 100, PQ-Box 150 PQ-Box 200 and PQ-Box 300.

6. Hardware Calib-Box

6.1 Operating conditions

- ▶ **operating temperature range:** 0°C ...45°C
- ▶ **storage temperature range:** -10°C ...+60°C
- ▶ **reference conditions:** 23°C ± 2K
- ▶ **IP-class:** IP20
- ▶ **rated voltage reference voltage input:** 230VAC (50Hz)

Input:

Voltage inputs L1, N from calibrator: L1, N = 230V AC (50Hz)



DANGER!

Danger to life due to electric shock!

The maximum voltage on the input lines (blue, red) must not exceed 230V to earth.

- Make sure that the device is not operated above the rated data



DANGER!

Danger to life due to electric shock!

- ➡ Connect the high potential to the red line and the low potential to the blue line at the output of the calibrator.



DANGER!

Danger to life due to electric shock!

Do not connect the voltage input of the device to the supply network.

Only suitable for connection to a calibrator.



WARNING!

Defect due to short circuit

- ➡ Always secure the device against short-circuit with the supplied fuse adapter for test leads.
- ➡ A fuse with the following values must be used: 80mA FF

- ▶ **rated current reference voltage input:** 1,25mA
- ▶ **voltage output L1, L2, L3, N, PE:** 230V (50Hz)



DANGER!

Danger to life due to electric shock!

Dangerous voltages can be present on all safety banana sockets.

- Make sure that only safety banana plugs are used

- ▶ **Current output: L1, L2, L3, N = 100mV (50Hz) for mini clamp input and Rogowski clamp input**



Maximum voltage of the current inputs to ground = 30 V rms



WARNING!

Personal injury and damage to property due to non-observance of the safety regulations

- ➡ **The maximum voltage of the current inputs of PQ-Box is 30 V rms to ground**

The current output signal is coming from a voltage divider from 230V to 100mV output

- ▶ **Power supply PQ-Box 150/200/300:** 15V DC
- ▶ **Power supply PQ-Box 50/100:** 100V - 230V AC/DC

6.2 Requirements for calibration equipment

According IEC61000-4-30 class A the PQ-Box have an accuracy of < 0.1% for voltage measurement.

We specify the following accuracy as a minimum for adjustment of PQ-Box.

Reference multimeter = 0,02% or better for AC voltage measurement

(for example: Fluke 8508A)


The calibrator has to deliver a sinus signal with 230V (50Hz) and a THD < 0,1%.

6.3 Calibration conditions

Appropriate storage time and period to warm up at ambient conditions have to been kept. The PQ-Box should be calibrated with normal operating temperature. Please run the PQ-Box 30 minutes before starting the calibration process.

The ambient conditions should be at a temperature of 23 ± 2 °C and a relative humidity of 60 ± 10 %.

6.4 Overview of the Calib-Box



6.5 PQ-Box connection to Calib-Box

- ✎ Connect the Calib-Box to the calibrator output with 230V AC (50Hz). Use the red and blue voltage leads.
- ✎ Connect Calib-Box to power supply 230V AC and switch the box on.
→ LED “ON” lights
- ✎ Connect the power supply to the PQ-Box
- ✎ Connect PQ-Box voltage leads to L1, L2, L3, E/N, E
→ Display of PQ Box 150/200/300 show L1, L2, L3 with 230V
- ✎ Connect current input adapter from Calib-Box with PQ-Box
- ✎ Connect AUX input adapter from Calib-Box with PQ-Box 200/300
(only available for PQ-Box 200 and 300)
- ✎ Connect one or two multimeter to DVM CH1 and DCV CH2





If you use only one multimeter connect to DVM CH1.

During the calibration process you have to change to DVM CH2



Connection of voltage leads PQ-Box for calibration

 Change the position of the blue voltage lead from “E/N” to “N” for calibration



All voltage channels will be calibrated parallel to 230V AC. We measure all four channels L1, L2, L3 and N to earth. In this position the display of the PQ-Box shows 0V.

7. Software PQCalib

The software PQCalib is designed for an easy calibration and adjustment of PQ-Box 50, PQ-Box 100; PQ-Box 150; PQ-Box 200 and PQ-Box 300.

The user can select any calibrator or multimeter. The calibration equipment is not mandatory for the calibration software.

Please note our minimum accuracy for the calibration equipment you are using.




Return the PQ-Box to the default setting before starting the calibration procedure

Start window of the software PQCalib

PQCalib - 1.100



PQ Box 200 trenner ComPort COM7 

Angaben prüfen und mit OK bestätigen

Prüfer

Ort

Sprach

Multimeter Ser.No.


Test-No. Zertifikat


Kalibrierdatum

Multimeter Ser.No.

Test-No. Zertifikat

Kalibrierdatum

 Fill your name and location

 Change the language to English

 Fill out the technical data of the used equipment

 Connect PQ-Box with USB cable to the PC

 Select the ComPort, e. g.

(if the PQ box is connected, the correct port will be displayed automatically)

 Press the button

 Press the button

7.1 Calibration of PQ-Box

If the PQ-Box is connected, the calibration process can be started.

Choose the option “Start Calibration” or “Start Adjustment”

- ▶ **Start calibration:** here the calibration factors of the PQ box are retained and will be not overwritten. This way you get a statement about the measurement error of the connected PQ box.


- ▶ **Start Adjustment:** The PQ-Box will be adjusted here.

Internal calibration factors will be overwritten with new factors.

PQCalib - 1.100





disconnect PQBox20 ComPort COM7 ▼


Standby - PQBox connected a-eberle 


SerNo. 1550-108 TR


Start Calibration Start Adjustment


Preparing Adjustment 

Adjustment of Voltage 8 

Adjustment of Rogowsk 

Checking Plausibility 

Test Measurement 


Result 

Cancel

Report


Quit



7.2 Start of PQ Box adjustment


- 1) press the button 

→ the screen with online values of PQ-Box appear

PQCalib - 1.100






Please check the data and press OK


Change to 230/50Hz and check the values on (

U1	230.71	V	I1	24.230	A
U2	230.69	V	I2	26.722	A
U3	230.46	V	I3	2.6459	A
UN	230.55	V	IN	3.8767	A

Multimeter 229.821 V

Multimeter 99.867 mV -9.99°









These values do not show the last accuracy of the PQ-Box. These are the measurement values without any calibration factor.

- 2) Fill out the measurement values from the high accuracy multimeter.

If you use one multimeter, you can change from DVM CH 1 to CH 2.




A dialog box with a white background and a blue border. It contains two rows of input fields. The first row is labeled 'Multimeter Ch 1' and contains a text box with the value '229.75' followed by a unit selector dropdown set to 'V'. The second row is labeled 'Multimeter Ch 2' and contains a text box with the value '99.74' followed by a unit selector dropdown set to 'mV'. At the bottom left is a 'Cancel' button and at the bottom right is an 'OK' button.


- 3) Press  if all values are entered

- 4) Please switch on Calib-Box from clamp to Rogowski.


Now additional to the current clamp input of the PQ-Box also the Rogowski input will be adjusted.



- 5) Switch back the Calib-Box from Rogowski to clamp





- 6) The software automatically starts a test measurement to calculate the error of the voltage and current input.




- 7) If all values are within the specified accuracy, the result shows green.

If one value will be out of the specified accuracy, the result shows a red warning.



- 8) With the button  a two page calibration report will be created.
- 9) This report can be printed or stored as a PDF file.

PQCalib - 1.002



Prüfzertifikat

Prüfzertifikat
3

Hiermit bestätigen wir, dass
veröffentlichten Spezifikationen
Messeinrichtungen werden regeln
auf nationale und internationale
Kalibriertechniken erreicht werde
unverändert weiterverarbeitet we

Prüfzertifikat test certificate
36511305103

Umgebungsbedingungen environmental conditions
Messungen entspricht DIN EN 60068-1
Measurements taken corresponds to EN 60068-1

Temperature: 15 °C ... 35 °C
Relative air humidity: 25 % ... 75 %
Pressure: 86 kPa ... 106 kPa

PQCalib Rev.1.002

Back

Print

A. Eberle GmbH & Co. KG

Frankenstraße 160
D-90461 Nuernberg

Tel.: +49 (0) 911 / 62 81 08-0
Fax: +49 (0) 911 / 62 81 08 96
E-Mail: info@a-eberle.de

<http://www.a-eberle.de>

Software - Version:
