

Import Control System (ICS) for airfreight consignments

For deliveries to:

A. Eberle GmbH & Co. KG
Frankenstr. 160
DE-90461 Nürnberg
Germany

contact person: Ms. Sabine Wight
phone: 0049 911 628108 - 81
email: sabine.wight@a-eberle.de

Dear customer,

In order to avoid delays for the import clearance of the consignment please include the following information in your proforma invoice

- 1) Number of boxes/packages and weight.
- 2) Precise material description, mentioning article-no. and serial-number if possible.
- 3) The first four digits of the **HS codes / customs tariff no.**

For voltage controllers REG-D(A)/REG-DP(A), systems and accessories for these devices:

90328900

For Earth fault detection devices and systems, power quality devices and systems, and PQ Boxes (EOR-D, EDCSys, PQI-D(A), PQ Box, PQI-DA smart) and accessories for these devices :

90303200

LVRSys Control cabinet:

85371098

Current Injection CIF

85045000

- 4) Complete address of consignor and consignee.
- 5) Our EORI-No.: DE 3485676.
- 6) When returning a faulty product, give us information prior to the return of the material. You will then get a RMA number (return of material authorisation) from us which should be mentioned in the documents.
Don't forget to tell us what is wrong with the device.

Thank you for your cooperation.

Should you have any further questions, feel free to contact us by e-mail: sabine.wight@a-eberle.de